

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS MANAGEMENT

DEP USE ONLY
Inspection Record #: 2891641
Enforcement Record #:
Complaint Record #:

SURFACE ACTIVITIES INSPECTION REPORT

DEP Office	California Oil & Gas Office	Inspection Type	PF
Address	25 Technology Drive, California Technology Park	Permit or Reg. #	051 - 24652
Addr Cont	Coal Center, PA 15423	ESCGP#	
Oper. Name	CHEVRON APPALACHIA LLC	Site #	790607
Oper. Address	700 CHERRINGTON PKWY, CORAOPOLIS, PA, 15108-4315	Project #	
Resp. Official Name	BA Lambie	Farm Name & Well #	YODER 1H
Resp. Official Phone		Other Info	
Latitude	39.97569	Longitude	-79.92387
County	Fayette	Municipality	Luzerne Township
Inspection Code	RTNC - Routine/Complete Inspection	Facility	
Permits / Auth	Well Permit	Site Phase	Drill/Alt
Well Info	Unconventional	Well Kind & Description	

REMARKS:

On 6/6/19 a routine complete inspection of the Yoder Well Pad was completed in response to activity observed on the well pad. The following was observed: >>Multiple pipe racks, pieces of contaminated equipment, and refuse containers were observed throughout the site being stored without secondary containment. Stains and visibly spilled material were found around and under several instances. Dark stains suggestive of spilled production fluids were found on the pad in multiple locations as well. This constitutes a violation of 25 Pa. Code § 78.54, 25 Pa. Code § 78.57(a), and 58 Pa. C.S. § 3218.2(d) in that the operator failed to control regulated materials in a manner that prevents pollution to the ground and Waters of the Commonwealth and that the conditions of the containment do not meet the required requirement for 110% capacity.

Inspection Results	Files Attached	Photos Attached	Date Inspected
NOVIO - No Violations Noted		✓	06-06-2019 03:21 PM

INSPECTOR SIGNATURE

KRISTOFER EICHENLAUB, Water Quality Specialist

Arrival Date: 06/06/2019 03:21 PM Depart Date: 06/06/2019 03:21 PM

Inspection Images

Image_1559848869743



Photo # 1. A bag containing contaminated refuse and equipment was found near the parking/staging area near the site entrance.





Photo # 2. A dark stain found behind a trailer on the north side of the site.

Image_1559848870161



Photo # 3. An equipment rack found without containment, note multiple small stains under rack.





Photo # 4. An additional bag of contaminated materials found stored without containment near the south east corner of the pad.

Image_1559848870555



Photo # 5. A second equipment rack found without containment, note staining under equipment.



Image_1559848870738

Photo # 6. A section of heavily contaminated grating was found stored off containment on the southern side of the pad.

Image_1559848870930



Photo # 7. A contaminated hose stored off containment on the southern side of the pad.

Image_1559848871132



Photo # 8. Staining on the pad gravel on the southern edge of the pad.

Image_1559848871360



Photo # 9. Additional staining along the southern edge of the pad.

Image_1559848871581



Photo # 10. Multiple bags of contaminated refuse and equipment found stored in the south west corner of the pad.

Image_1559848871784



Photo # 11. Additional refuse bags and a generator powered light were also noted in the south west corner of the pad without containment.

Image_1559848871985



Photo # 12. A stain along the western edge of the pad.